



# Atellio family: NCP105

## Firmware and AUDAC Touch™ update

We would like to bring you another update about the Atellio family. Please make sure you are always running the latest version of AUDAC Touch™. You can find the latest versions here: <https://audac.eu/eu/software/audac-touch>

### Released March 2026

NCP105 firmware version: 1.3.0

#### New features

- Brightness of display LEDs can now be adjusted from AUDAC Touch™

### Released August 2025

NCP105 firmware version: 1.2.1

#### New features

- Legacy device support (MTX48/88, M2, MFA208/216, AMP523, AMP203, VEXO, SMA/Q, PMA/Q).
- Improved status displays.
  - Button LEDs with layer indication.
  - Multiple LED ring indications: Volume/Mute/Route of a zone controlled by rotary will be shown on the LED ring.
    - Rotary volume control: Volume is shown continuously; routing is shown temporarily when changed.
    - Rotary volume control: If a zone is muted, the LED ring shows red; when unmuted, it shows volume.
    - Rotary routing control: Routing is shown continuously; volume is shown temporarily when changed.
- Identify functionality: LED ring blinks for 10 seconds when the Identify button is pressed in the AUDAC Touch™ device list.

## Released Mid December 2024

NCP105 firmware version: 1.1.1

### New features

- More responsive rotary on NCP105 for volume changes

## Known limitations for the latest version

NCP105 firmware version: V1.1.1

- Will initially only work with the LUNA & the NWP series.
- The devices to control should have a static IP address.

## Released end of May 2024

NCP105 firmware version: 1.1.0

### New features

- Improved touchpad driver including configurable sensitivity
- Atellio family mixer control support
- Link local IP configuration support

### Bug fixes

- Fixed Consenso control trough commander (device not accepting more than one command)

## Released December 6<sup>th</sup> 2023

NCP firmware version: 1.0.4

### New features

- Luna GPO triggering via Luna event handler and NCP105
- Event handler settings backup and restore via file browser
- NCP105 supports custom (single) commands via commander function in AUDAC Touch™ for, Atellio family\*, Consenso family\* & third-party equipment. No visual feedback yet for custom commands via the Commander function.

## Released October 31<sup>st</sup> 2023

NCP105 firmware version: 1.0.2

### New features

- Firmware updates of NCP105 and NWP Series via AUDAC Touch™ on the same network.
- NCP105 button auto-calibration
- NCP105 bug fixes
  - Improved stability for simultaneous use of buttons

## Released: September 13<sup>th</sup> 2023

NCP105 firmware version: 1.0.1

### New features

- VU indication for all the Atellio family products.
- Increased NCP105 rotary volume control steps from 1dB to 3dB. No NCP firmware update needed, only reprogramming rotary via Audac Touch.

## Released August 31<sup>st</sup> 2023

NCP105 firmware version: 1.0.1

### New features

- NCP105 configuration support in AUDAC Touch™.
- NCP105 rotary configuration with combined volume and mute (Configure rotary button to volume),
- Device connection indication on settings screens in Touch.
- IP address configuration without Touch restart.
- Connection status of the Atellio family products.